



Photograph B-11. Possible knickzone in Peju Provinces and Round Pond Reach



Photograph B-12. West side incised tributary at Wilsey property



Photograph B-13. Looking downstream on west side tributary, Wilsey property



Photograph B-14. Round Pond south of Rutherford Rd from the Wilsey property, stage 5



Photograph B-15. Undercut rip rap protection on the Wilsey property (west bank), stage 5 outside bend



Photograph B-16. Within the Wilsey property - east bank from west bank, stage 6