



Photograph B-41. East bank, Carpy Connoly from north end of C Mee property



Photograph B-42. East bank, Carpy Connoly from north end of C Mee property, stage 5



**Photograph B-43. Bank erosion on the southern boundary of Quintessa, from southern boundary of Frogs Leap
One of the three top priority restoration sites. stage 4 outside bend.**



Photograph B-44. Bank erosion on the southern boundary of Quintessa, from southern boundary of Frogs Leap, stage 4



Photograph B-45. Local bank erosion mid way up the Frogs Leap property, Quintessa on far bank, stage 4



Photograph B-46. Bank erosion on the Quintessa property, from mid way up Frogs Leap



Photograph B-47. Rip rap protection on the Quintessa property, opposite mid point on Frogs Leap



Photograph B-48. Steep west bank on mid section Frogs Leap