
Appendix B

Images of the Napa River, Rutherford Reach





Photograph B-2. Southern end of Wilsey property, stage 5 but with erosion on outside (east) bend



Photograph B-3. Bank collapse on Sequoia Grove property

One of the priority restoration sites, this reach is stage 5, but receives impinging flows.



Photograph B-4. Looking from Sawyer to Wilsey properties