



Photograph B-3. Bank collapse on Sequoia Grove property
One of the priority restoration sites, this reach is stage 5, but receives impinging flows.



Photograph B-4. Looking from Sawyer to Wilsey properties



Photograph B-5. Looking from the Sawyer to Wilsey properties, stage 5 with terrace development



Photograph B-6. From southern end of St Supery to Wilsey property, stage 6 with vegetated terraces



Photograph B-7. Looking from the central St Supery to Wilsey properties, stage 6



Photograph B-8. Looking from the northern St Supery to Wilsey properties, stage 6 but in need of revegetation



Photograph B-9. Northern boundary of St Supery and Wilsey properties, moving into stage 5



Photograph B-10. Southern boundary of the Round Pond property from the west bank, stage 5