

Photograph B-23. MacDonnel property from Round Pond - "Early" narrow stage 5 reach



Photograph B-24. MacDonnel from Round Pond

 $P:\Projects\1638-02-Napa-River-Rutherford-Restoration\Final report\1638-02-Napa-River-Report-Final.doc$



Photograph B-25. Honig property from Round Pond, widening stage 4 Reach



Photograph B-26. Round Pond and Honig properties This confined stage 4 section is the priority reach for restoration.

 $P:\Projects\1638-02-Napa-River-Rutherford-Restoration\Final report\1638-02-Napa-River-Report-Final.doc$



Photograph B-27. Honig from boundary of Round Pond and E Mee



Photograph B-28. Bank erosion on E Mee property opposite Honig, within the priority restoration reach

 $P:\Projects\1638-02-Napa-River-Rutherford-Restoration\Final report\1638-02-Napa-River-Report\Final.doc$