


Photograph B-35. Incised stage 4 channel with bank top erosion, Carpy Connoly The northern boundary of the main priority reach.





Photograph B-37. Area of potential banktop restoration between levees, C Mee





Photograph B-39. Looking across the riparian woodland from C Mee to Carpy Connoly, stage 5



Photograph B-40. Local bank erosion on the east bank, Carpy Connoly